


Figure 1: Software-RAID1 correctly implemented and running




Figure 2: defective Software-RAID1 after 2 new starts of PC (first without attached USB-RAID - then again with attached USB-RAID)